


Fig. 1 (PRIOR ART)










Fig. 3

List of Possible Resources: • physical workspace ← ω

- shared I/O ~12
- transport devices ~ ┗⁴
- changeable tooling ~↓↓
- sensor systems ~
- process stations ~70
- end of arm tooling 32
- technology controllers ~74

152

